SERVICE TAX INVOICE

BRIAN HILTON PEUGEOT

Service Department
600 Pacific Highway
North Gosford NSW 2250

T 02 4328 2888
service@brianhilton.com.au
brianhiltonpeugeot.com.au

ABN: 20 107 210 429
MD 045900, MVRL 50623

ACN: 163 099 198
ARC: AU01773

REPAIR ORDER No: JC54008416

PAGE: 1

C1 Customer (Cash)

Guest: [redacted]

DATE:	TIME IN:	TIME OUT:	KILOMETERS:	ADVISER:
11/03/2026	8:00 AM	5:00 PM	172813	CS

VEHICLE: 2018 Peugeot 3008 GT LINE 6 SP AUTOMA

MONTH/YEAR AIR:

REG. No:	STOCK No:	SELLING DEALER:
DTW49U	6002681	1260

GUEST No: 609504

VIN: VF3M45GYWJS056689

ENGINE No: FJCG2411211

CONTACT NAME: [redacted]

COLOUR/TRIM: Nera Black - Metallic Paint/

ORDER No:

NUMBERS: [redacted]

WAR. EXP:	WAR. KM:	EXT.WAR.EXP:	EXT.WAR.KM:	RDR Date:
10/04/2021				

		PRICE	QTY/HRS	AMOUNT
JOB DETAILS				
JOB 1	"A" SERVICE (108MTH/180000KM) AS PER MENU PRICE SERVICE GUIDELINES $854.80			362.20

Carry out an exterior inspected of the vehicle at time of drop off.
Checked the engine oil level.
Drained the engine oil and replaced the oil filter.
Replaced the sump plug washer and refill the engine oil to the correct level.
Replaced the pollen filter.
Checked the battery condition and electrolyte level.
Checked the windscreen washer fluid level.
Checked the power steering fluid level and its condition.
Checked the state of the hydraulic circuit, hoses and cylinders.
Checked the condition of all protective rubber boots.
Checked the condition and tension of the accessory belt/s.
Checked the coolant level is to the MAX mark and state of associated components.
Checked the brake fluid level.
Checked the shock absorbers for leakage.
Checked the condition and free-play in the hubs, tie rods, ball and elastic joints.
Checked the condition of the front and rear brake pads and discs.
Checked the condition of the tyres and their pressures (including spare).
Checked the condition and operation of all lights and lenses.
Checked the condition of the wiper blades.
Checked the condition of the window glass and rear view mirrors.
Checked horn operation.
Checked the operation of the windscreen washer jets.
Checked the operation of the interior lights and warning lights.
Check the brake and clutch pedal operation.
Checked handbrake operation and adjustment.
Carry out an electronic management system Global Test with the Peugeot Planet diagnostic system as required.
Completed the Peugeot Service Interval checked sheet
Road test vehicle.
Checked the Coolant condition with Ph test strips. - Replace coolant if pH lower than 6.3
Replaced ancillary drive belt
Check exhaust system and fixings
Reset the Service Indicator on the Instrument Panel
Checked the radiator and heater hoses
Checked pipes and housings sealing and condition
Checked the status of preventative maintenance campaigns - mandatory action as prescribed by Automobiles Peugeot.

****

********** CONTINUED **********

VEHICLE RELEASE

WORK EXPLAINED VEHICLE WASHED FLOOR MAT SECURITY EXPLAINED
COST EXPLAINED ALL COURTESY ITEMS REMOVED

DELIVERED BY :..... DATE:.....

RECEIVED BY :..... TIME:.....

PREFERRED CONTACT METHOD: LETTER PHONE DO NOT CONTACT EMAIL MOBILE/SMS

CASH ACCOUNT EFTPOS/CREDIT CARD

AMOUNT RECEIVED WITH THANKS :

RECEIVED BY

SERVICE TAX INVOICE

BRIAN HILTON PEUGEOT

Service Department
600 Pacific Highway
North Gosford NSW 2250

T 02 4328 2888
service@brianhilton.com.au
brianhiltonpeugeot.com.au

ABN: 20 107 210 429
MD 045900, MVRL 50623

ACN: 163 099 198
ARC: AU01773

REPAIR ORDER No: JC54008416

PAGE: 2

C1 Customer (Cash)

Guest: [redacted]

DATE:	TIME IN:	TIME OUT:	KILOMETERS:	ADVISER:
11/03/2026	8:00 AM	5:00 PM	172813	CS

VEHICLE: 2018 Peugeot 3008 GT LINE 6 SP AUTOMA

MONTH/YEAR AIR:

REG. No:	STOCK No:	SELLING DEALER:
DTW49U	6002681	1260

GUEST No:	VIN:	ENGINE No:
609504	VF3M45GYWJS056689	FJCG2411211

CONTACT NAME: [redacted]

COLOUR/TRIM: Nera Black - Metallic Paint/

ORDER No:

CONTACT NUMBERS: [redacted]

WAR. EXP:	WAR. KM:	EXT.WAR.EXP:	EXT.WAR.KM:	RDR Date:
10/04/2021				

JOB DETAILS				PRICE	QTY/HRS	AMOUNT
	Brake report:					
	Front left: 8mm		Front right: 8mm			
	Rear left: 3.5mm		Rear right: 3.5mm			
	Tyre report:					
	Front left: 3.8mm		Front right: 4.0mm			
	Rear left: 1.0mm		Rear right: 1.2mm			
PRT	NG	SCREENWASH	WINDSCREEN WASHER FLUID		1	2.32
PRT	PEU	9821501880	PASS COMPART ANTI-ALLERG FILT		1	67.36
PRT	PEU	031338	ENGINE DRAINING PLUG GASKET		1	2.72
PRT	PEU	1611627180	ANCILLARY BELT ROLLER KIT		1	191.47
PRT	NG	R2663P	Oil Filter Element		1	37.15
CON	5W30 QINEO HTC					77.37
MIS	Environmental Levy					20.00
MIS	Workshop Sundries					16.50
			JOB 1 SUBTOTAL			**777.09**

JOB DETAILS

JOB 2 INSPECT VEHICLE FOR PINK SLIP — 46.36

Inspected vehicle for pink slip

Failed vehicle requires tyres and control arms refer to recommendations.

JOB 2 SUBTOTAL — **46.36**

JOB DETAILS

JOB 3 C/S WATER STILL LEAKING FROM SUNROOF - WHEN RAIING HEAVILY OR BEEN SITTING IN THE RAIN FOR SOME TIME - PLEASE ASSESS

********** CONTINUED **********

VEHICLE RELEASE

PREFERRED CONTACT METHOD: LETTER PHONE DO NOT CONTACT EMAIL MOBILE/SMS

WORK EXPLAINED VEHICLE WASHED FLOOR MAT SECURITY EXPLAINED

COST EXPLAINED ALL COURTESY ITEMS REMOVED

DELIVERED BY :..... DATE:.....

RECEIVED BY :..... TIME:.....

CASH ACCOUNT EFTPOS/CREDIT CARD

AMOUNT RECEIVED WITH THANKS :

RECEIVED BY

SERVICE TAX INVOICE

BRIAN HILTON PEUGEOT

Service Department
600 Pacific Highway
North Gosford NSW 2250

T 02 4328 2888
service@brianhilton.com.au
brianhiltonpeugeot.com.au

ABN: 20 107 210 429
MD 045900, MVRL 50623

ACN: 163 099 198
ARC: AU01773

REPAIR ORDER No: JC54008416

PAGE: 3

C1 Customer (Cash)

Guest: [redacted]

DATE:	TIME IN:	TIME OUT:	KILOMETERS:	ADVISER:
11/03/2026	8:00 AM	5:00 PM	172813	CS

VEHICLE: 2018 Peugeot 3008 GT LINE 6 SP AUTOMA

MONTH/YEAR AIR:

REG. No:	STOCK No:	SELLING DEALER:
DTW49U	6002681	1260

GUEST No: 609504

VIN: VF3M45GYWJS056689

ENGINE No: FJCG2411211

CONTACT NAME: [redacted]

COLOUR/TRIM: Nera Black - Metallic Paint/

ORDER No:

NUMBERS: [redacted]

WAR. EXP:	WAR. KM:	EXT.WAR.EXP:	EXT.WAR.KM:	RDR Date:
10/04/2021				

JOB DETAILS **PRICE** **QTY/HRS** **AMOUNT**

Carried out water test on the vehicle:

- Could not find any leakage of water from the roof at time of the water test.

All okay at time of service.

JOB 3 SUBTOTAL **NO CHARGE**

JOB DETAILS

JOB 4 C/S A/C DOESN'T HEAT UP, TAKES MORE THAN 20 MINUTES TO WARM UP - PLEASE ASSESS

Carried out inspection on vehicle:

- Found that the heater core/cooling system is clogged.

- Requires removal and repalcement of the heater core.

Refer to recommendations.

JOB 4 SUBTOTAL **NO CHARGE**

RECOMMENDATIONS

To replace the front lower control arm the left hand front has a deep gouge and unusal wear.
** Supply and fit of the front lower control arms $2,140.00 inc GST.*
** Parts $1,364.00 inc GST.*
** Labour $740.00 inc GST.*

To replace the water pump due to the water pump leaking coolant.
** Supply and fit of the water pump $961.00 inc GST.*
** Parts $400.00 inc GST.*
** Labour $555.00 inc GST.*

To replace the valve cover due to leaking oil heavily.

********** CONTINUED **********

VEHICLE RELEASE

PREFERRED CONTACT METHOD: LETTER PHONE DO NOT CONTACT EMAIL MOBILE/SMS

WORK EXPLAINED VEHICLE WASHED FLOOR MAT SECURITY EXPLAINED

COST EXPLAINED ALL COURTESY ITEMS REMOVED

DELIVERED BY :..... DATE:.....

RECEIVED BY :..... TIME:.....

CASH ACCOUNT EFTPOS/CREDIT CARD

AMOUNT RECEIVED WITH THANKS :

RECEIVED BY

SERVICE TAX INVOICE

BRIAN HILTON PEUGEOT

Service Department
600 Pacific Highway
North Gosford NSW 2250

T 02 4328 2888
service@brianhilton.com.au
brianhiltonpeugeot.com.au

ABN: 20 107 210 429
MD 045900, MVRL 50623

ACN: 163 099 198
ARC: AU01773

REPAIR ORDER No: JC54008416

PAGE: 4

C1 Customer (Cash)

Guest: [redacted]

DATE:	TIME IN:	TIME OUT:	KILOMETERS:	ADVISER:
11/03/2026	8:00 AM	5:00 PM	172813	CS

VEHICLE: 2018 Peugeot 3008 GT LINE 6 SP AUTOMA

MONTH/YEAR AIR:

REG. No:	STOCK No:	SELLING DEALER:
DTW49U	6002681	1260

GUEST No:	VIN:	ENGINE No:
609504	VF3M45GYWJS056689	FJCG2411211

CONTACT NAME: [redacted]

NTA T NUMBER : [redacted]

COLOUR/TRIM: Nera Black - Metallic Paint/

ORDER No:

WAR. EXP:	WAR. KM:	EXT.WAR.EXP:	EXT.WAR.KM:	RDR Date:
10/04/2021				

JOB DETAILS	PRICE	QTY/HRS	AMOUNT

** Supply and fit $890.00 inc GST.*

To replace the coolant expansion tank.
** Supply and fit $325.00 inc GST.*
** Parts $140.00 inc GST.*
** Labour $185.00 inc GST.*

To replace the heater core due to blockage
** Supply and fit $1,060 inc GST.*
** Parts $320.00 inc GST.*
** Labour $740.00 inc GST.*

To replace the rear brake pads and rotors.
** Supply and fit $1,134.00 inc GST genuine parts.*

Quote number OR53013601.

To replace x2 tyres awaiting quote or refer to tyre plus.

****** Next service due: 02/02/2027 or odometer reading: 182000 whichever comes first.**

LABOUR	**$408.56**
CONSUMABLES	**$77.37**
PARTS	**$301.02**
MISCELLANEOUS	**$36.50**
SUBTOTAL	**$823.45**
GST	**$82.35**
TOTAL INCLUDES GST	**$905.80**

PRINTED 17/08/26 13:39:03

VEHICLE RELEASE

PREFERRED CONTACT METHOD: LETTER PHONE DO NOT CONTACT EMAIL MOBILE/SMS

WORK EXPLAINED VEHICLE WASHED FLOOR MAT SECURITY EXPLAINED

COST EXPLAINED ALL COURTESY ITEMS REMOVED

DELIVERED BY :..... DATE:.....

RECEIVED BY :..... TIME:.....

CASH ACCOUNT EFTPOS/CREDIT CARD

AMOUNT RECEIVED WITH THANKS :

RECEIVED BY