
Reference: R271280 29/10/2026 Version 1

Karen Robinson 3008 2WD SUV GT-line 1.6L T/P 120kW THP EAT6 DTW49U VF3M45GYWJS056689




Registration Number :	DTW49U
Service Advisor :	Megan Brisenden
Technician :	Mabini Querijero
Odometer :	180020

Your technician recommends the listed operations for your vehicle. Select "Accept" for the items you want to have completed. When you select "Accept" you agree to the nominated work at the specified rates. Select "Authorise Now" when you have completed the form.

Urgent Recommended Ok Not Checked

	Operation	Description	Price	Authorisation
		DIAGNOSE		Pre-booked
	Engine Components	Scanned for codes, found P1338 00 - Misfire on cylinder 2. Replaced all spark plugs and fault code still there. Checked with endoscope found cylinder 2 has broken and holes in the exhaust valve with deep scratches on cylinder wall. Vehicle requires a new engine to rectify. - THIS COMES WITH 2 YEAR WARRANTY, PART IS COMING FROM FRANCE		Pending Authorisation



Inspection Images



	Bodywork			

Totals		
Identified:		
Pre-booked:		
Authorised:		
GST		
Amount Outstanding:		

Enter comments or questions

Signature

Clear