

SN: 9TDP80622599

Time: 09/17/2025 22:04:01

Customer Name: N/A

Customer Phone: N/A

Customer Email: N/A

Technician Name: N/A

Notes: car had the engine removed for work at another garage and now the radio,screen, plus heaters do not work.

Shop Name: mike	Telephone: N/A
Email: mikebowden25@hotmail.co.uk	Country: N/A
State: N/A	City: N/A
Address1: N/A	Address2: N/A

Make: CITROEN	Model: DS4
Year: 2013	VIN: VF7NX9HD8DY524295
Odometer: 123994 km	License #: YD13YTH

Pre-Scan

09/17/2025 22:04:01

System(20)	Status(16)
Built-in System Interface (BSI)	Fault 8
Engine System	Fault 2
Anti-lock Brake System	Fault 1
Airbag	No Fault
Power Steering Electric Pump Unit	No Fault

Multiplexed Additive Adding Pump	No Fault
Battery Charge Status Unit	No Fault
Electric Secondary Brake	Fault 1
Engine Wiring Housing	Fault 1
Control Panel	No Fault
Parking Assistance	No Fault
Air Conditioning ECU	Fault 1
Switch Module Under Steering Wheel	No Fault
Anti-theft Alarm	Fault 1
Driver's Door Control Panel	No Fault
Matrix Screen Integral To The Instrument Panel	No Fault
Rain And Brightness Sensor	Fault 1
Multiplexed Control Panel	No Fault
Steering Wheel With Integral Controls(Vci)	No Fault
Supply Protection And Management Unit	No Fault

DTC

System	Code	Description	Status
Built-in System Interface (BSI)	B1003	Configuration Fault	Present
Built-in System Interface (BSI)	U1F00	Fault Event Not Stored In The Faults Log	Present

Built-in System Interface (BSI)	B1163	Number Plate Lighting Control Fault	Present
Built-in System Interface (BSI)	B115F	Front Courtesy Lamp Control Fault	Present
Built-in System Interface (BSI)	B162C	Accessories Positive Relay Control And Status Not Coherent	Present
Built-in System Interface (BSI)	U1F23	Absence Of Communication With The Multifunction Display	Present
Built-in System Interface (BSI)	U1F26	Absence Of Communication With The Audio Amplifier	Present
Built-in System Interface (BSI)	U1F20	No Communication With The Car Radio	Present
Engine System	P2291	Starting Monitoring. The Rise In Pressure In The Injection Rail Is Too Slow On Starting	Intermittent
Engine System	P0685	Power Relay Control. Open Circuit	Intermittent
Anti-lock Brake System	U1219	Fault Automatic Release Of The Electric Parking Brake. Data Invalid	Permanent Fault
Electric Secondary Brake	C1555	Fault In The Activation / Deactivation Control Of The Electric Parking Brake . Short Circuit To Positive Or Short Circuit To Earth	Permanent Fault
Engine Wiring Housing	B1138	Fault LH Dipped Beam	Temporary Fault
Air Conditioning ECU	B131C	Passenger Compartment Air Blower Fault	N/A
Anti-theft Alarm	P0EE3	Supply Fault (Siren Faulty)	Local.
Rain And Brightness Sensor	U1807	Park Information Fault	Temporary Fault