

Diagnostic Report

12/08/2025

Dollarfix

VIN: VF3L35FVGES029395

Date: 12/08/2025

Make: Peugeot 308(T9)

Odometer: 157943 miles

Year: 2014

Vehicle Software Version: V10.52

Scan Result

1765209140

System (26)	Status(13)
Built-In Systems Interface(Bsi)	No Fault
Engine ECU	Fault 2
Anti-Lock Braking System (ABS) Or Electric Stability Program (ESP)	No Fault
Air Bags	No Fault
Engine Wiring Housing	No Fault
Switch Module Under The Steering Wheel	No Fault
Headlamp Height Corrector	No Fault
External CD Player	Fault 1
Supply Protection And Management Unit	No Fault
Driver's Door Control Panel	No Fault
Power Steering GEP	Fault 2
Electronic Key Reader	No Fault
Electric Steering Lock	No Fault
Audio-Navigation Or Telematic Unit Or Connected Audio System	Fault 1
Vehicle Distance Assistance	No Fault

Air Conditioning	No Fault
Steering Wheel With Integral Controls(Vci)	No Fault
Multifunction Display	Fault 3
Rain/ Brightness Sensor	Fault 1
Parking Assistance	Fault 1
Battery Charge Status Unit	No Fault
Hands Free Control Kit	No Fault
Multiplexed Control Panel	Fault 1
Instrument Panel	Fault 1
Matrix Screen Integral To The Instrument Panel	No Fault
Seat Belt Not Fastened LED Unit(Tnb)	No Fault

DTC

System	Code	Description	Status
Engine ECU	U1218	CAN Network. Fault In Communication With The BSI ECU	Intermittent
Engine ECU	U1213	CAN Network. Fault In Communication With The ABS/ESP ECU	Intermittent
External CD Player	B1000	Calibration Downloading Fault	Permanent
Power Steering GEP	P0562	Power-on Fault. Not Characterised	Intermittent
Power Steering GEP	B1406	Overheating Of The Power Steering Motor Or ECU. Not Characterised	Intermittent

Audio-Navigation Or Telematic Unit Or Connected Audio System	0300	Calibration Downloading Fault. Resistance Too Low	Local
Multifunction Display	B1004	Touch Screen Internal Fault	Temporary
Multifunction Display	U1F3E	Absence Of Communication With The Telematic Unit	Temporary
Multifunction Display	U1F18	Touch Screen Not Communicating On The Multimedia CAN	Temporary
Rain/ Brightness Sensor	U1807	Park Information Fault	Temporary
Parking Assistance	B1242	Left-hand Rear View Mirror Warning Lamp Fault	Permanent
Multiplexed Control Panel	B1004	ECU Internal	Temporary
Instrument Panel	B1003	Secure Configuration Fault	Permanent