

Citroen_C4 PICASSO DTC Report



Company: Zoltan Feher

Mailbox: feher.zoltan.janos@gmail.com

Telephone: --

Website: --

Address: --

► Basic Information

VIN: VF7UD9HZH45086536

Mileage: 245304km

Plate No.: --

Report Date: 2026-06-03 20:29:49

SN: X100MAX-00985

Version: V5.7.79_12.05

Path: CITROEN->V13.20->Automatic Detection->C4 PICASSO->2004

► System Scan Result

25 systems detected: 5 systems related to fault codes, 11 fault codes

NO.	System Name	Status
1	Power Steering	▲ 5
2	Engine Wiring Housing	▲ 2
3	Built-In Systems Interface	▲ 2
4	Anti-lock Braking System (ABS) or Electronic Stability Program (ESP)	▲ 1
5	Automatic Or Piloted Manual Gearbox	▲ 1
6	Engine Management ECU	✓
7	Under-Inflation Detection	✓
8	Dynamic Headlamp Height Adjuster	✓
9	Battery Charge Status Control Unit	✓
10	Lane Wandering Alert	✓
11	Airbags and Pretensioners ECU	✓
12	Windscreen Wiper	✓
13	Controls Under The Steering Wheel	✓
14	Air Conditioning	✓
15	Instrument Panel	✓
16	Radio	✓

17	Anti-Theft Alarm	✓
18	Rain and Brightness Sensor	✓
19	Electric Secondary Brake	✓
20	Parking Assistance	✓
21	Pneumatic Suspension	✓
22	Trailer Relay Unit	✓
23	Driver's Door Module	✓
24	Interior Ambiance Lighting Control Unit	✓
25	Passenger Door Module	✓

► Trouble Code

Engine Wiring Housing (DTC Amount: 2)

NO.	DTC Code	Trouble Code Descriptions	Status
1	F000	Engine fuse box not communicating on the CAN fault	
2	F998	Fault: headlamp washer relay control	

Anti-lock Braking System (ABS) or Electronic Stability Program (ESP) (DTC Amount: 1)

NO.	DTC Code	Trouble Code Descriptions	Status
1	C1331	Front right wheel speed sensor signal fault.	

Automatic Or Piloted Manual Gearbox (DTC Amount: 1)

NO.	DTC Code	Trouble Code Descriptions	Status
1	U0415	Fault in the information transmitted by the ABS/ESP or EPB (Electric Parking Brake) ECU	

Built-In Systems Interface (DTC Amount: 2)

NO.	DTC Code	Trouble Code Descriptions	Status
1	F000	FaultEngine fuse box : ECU mute on the CAN	
2	F998	Engine fusebox : Fault in the headlamp wash control circuit	

Power Steering (DTC Amount: 5)

NO.	DTC Code	Trouble Code Descriptions	Status
1	U1305	Speed of rotation of the steering wheel information fault	

2	U1308	Fault absence of communication with the engine management ECU and the hybrid management ECU (If the hybrid management ECU is present)
3	U1108	Fault absence of communication with the engine management ECU and the hybrid management ECU (If the hybrid management ECU is present)
4	C1408	Vehicle speed data fault
5	C1178	ECU internal fault

* This report is only responsible for the results of this detection