



25/01/13 422101

SUSP CROSSMEMBR TORSION BAR RECESS DOOR

A) SEE INFO'RAPID C5: 3 N°6 OF 31/05/2002

B) SEE DEVELOPMENT BULLETIN IN PAPER FORMAT BRE 741F ADDITIVE N°6 OR BULLETINS ON CITROEN SERVICE B3FT0AP0 AND B3DS01P0 (REPAIR METHOD)



01/2013

00019578

01	5148 G9	01	REAR SUSPENSION CROSSMEMBER SEE B
02	5131 C7	02	REAR CROSSMEMBER FLEXIB JOINTS AV
03	5131 C8	02	REAR CROSSMEMBER FLEXIB JOINTS AR
04	5170 C0	01	REAR ANTI-ROLL BAR DIAM 21,5
05	5144 23	06	SCREW WITH BASE DIAM 12X175-55
06	5144 22	04	SCREW WITH BASE DIAM 14X200-45
07	3509 44	02	SUBFRAME FIXING SREW DIAM 12X175-150
09	7203 79 RP 7518 WQ	02 01	BLANKING CAP DIAM 35
10	5271 F7	02	SUSPENSION CYLINDER SUPPORT
11	9181 E0	02	SCREW DIAM 8X125-22
12	5133 25 LE-0501	02	PLAIN WASHER 12X87-3 - UNTIL RPO 09090 SEE A
13	5122 50 LE-0206 5122 51	02 02	VIBRATE WEIGHT - SINCE RPO 09091 UNTIL RPO 09332 SEE A DAMPER - SINCE RPO 09333 SEE A