


23/07/11 371135
DRIVE SHAFTS
1,905L AND 4X4

NOTE: AS REPLACEMENT PARTS, WE SUPPLY WITH THE ABS



01	3272 T1	NFP	01	DRIVE-SHAFT EXCHANGE LEFT MARKING 8GN63 8GN61 (8GN63) <i>- AGE >= 2</i>
02	3273 1L	NFP	01	DRIVE-SHAFT EXCHANGE RIGHT MARKING 8GN62 8GN64 (8GN64) <i>- AGE >= 2</i>
04	3293 91		02	DRIVESHAFT GAITER KIT <i>WHEEL SIDE (GAITER ID 9563146480/9604451080/9613556180)</i>
05	3293 59		02	DRIVESHAFT GAITER KIT <i>AXLE SIDE (MARK GAITER 9502508880)</i>
06	3248 04	NFP	01	DRIVE SHAFT BUSH LEFT 27 X 31,5 8
08	79 03 083 153		04	DRIVE SHAFT BOOT CLAMP LONG 240
09	96 995 619	NFP	02	TRANSMISSION SNAP RING
10	3297 00	RP 3297 33	04 01	WHEEL HUB FIXING NUT 24 X 150
11	3297 02	RP 3297 35	04 01	LOCKING NUT
12	3297 03		04	HOLDING PIN
13	3299 07		99	GREASE